

CERTIFICATION by CUSTODIAN of RECORDS Tucson Police Department Crime Laboratory

of Public Safety for a quality assurance program.
A quality assurance specialist (QAS) tested the instrument on the following dates. The acceptable accuracy limits, as defined in A.A.C. R13-10-104.A.2, for a 0.100AC solution are 0.090AC to 0.110AC.
Date: 2-26-2007 Cal 1 0,100 AC Cal 2 0.100 AC
Between the dates of $1 \cdot 26 \cdot 2007$ and $2 \cdot 26 \cdot 2007$ the instrument was operating properly and accurately.
The instrument was taken out of service for repair on The instrument was returned to service on
Terry S. Gallegos
March 12, 2007 ADPS QAS Permit # 33169
SUBSCRIBED AND SWORN to before me this, day of, 2007.
KATHY A. KINNEY NOTARY PUBLIC-ARIZONA PIMA COUNTY My Comm. Exp. Sept. 4, 2008 Notary Public

^{*}Includes documents specified in A.A.C. R13-10-104.A.5

EXHIBIT G-4

THIS REPORT PREPARED PURSUANT TO DUTY IMPOSED BY A.A.C. R13-10-104(A)

ARIZONA DEPARTMENT OF PUBLIC SAFETY

10f7 184 mm

STANDARD QUALITY ASSURANCE PROCEDURES INTOXILYZER MODEL 8000

STANDARD QUALITY ASSURANCE PROCEDURE

QA SPECIALIST LEVRY Gulleyos 28847 AGENCY Tucson Police Department DATE 2.26-2007 TIME 1112 INTOXILYZER SERIAL # 80-002261 LOCATION DVI HQ
DATE 2-26-2007 TIME 1112
intoxilyzer serial # 80-002261 Location DVI HQ
(/ 1. Display reads "PUSH BUTTON TO START"
DIAGNOSTIC TESTS
1. Clock time check. 2. Date check.
OPERATIONAL TESTS
1. Alcohol-free subject test result 0. 000 AC. 2. Error recognition logic system functioning. Not a Successfully Completed Test Sequence printed 3. Proper sample recognition system. Not a Successfully Completed Test Sequence printed Deficient sample printed. 4. Standard Calibration Check standard 0. 100 AC Result: 0. 100 AC
Instrument is operating properly and accurately. YESNO
COMMENTS
SIGNATURE Sum (all

DPS Form Exh G-4 (Rev. 05-01)

Location: TUCSON POLICE DEPT

Serial Number: 80-002261

02/26/2007

11:13:09

Standard Lot#: 627101G

Last Changed By: T. GALLEGOS #28847

QAS: T. GALLEGOS #28847

TUCSON PD CRIME LAB

Operator: T. GALLEGOS #28847

TUCSON PD CRIME LAB

Subject: SQAP, SQAP

DOB: 11/11/1111

Sex: F Weight: 111

15 Minute Deprivation Period? Yes

Test	g/210L	Time
Air Blank	0.000	11:14:01
Diagnostic Test	Pass	11:14:28
Air Blank	0.000	11:14:56
0.100 Cal Check	0.101	11:15:14
Air Blank	0.000	11:15:44
Subject Test	0.000	11:16:10
Air Blank	ABT*	11:16:20
Air Blank	0.000	11:16:48

^{*}Sequence Aborted

Not a Successfully Completed Test Sequence

2057 134 ms

Location: TUCSON POLICE DEPT

Serial Number: 80-002261

11:17:10 02/26/2007

Standard Lot#: 627101G

Last Changed By: T. GALLEGOS #28847 #28847 QAS: T. GALLEGOS

TUCSON PD CRIME LAB

#28847 Operator: T. GALLEGOS TUCSON PD CRIME LAB

Subject: SQAP, SQAP

DOB: 11/11/1111

Sex: F Weight: 111

15 Minute Deprivation Period? Yes

Test	g/210L	Time
Air Blank	0.000	11:17:59
Diagnostic Test	Pass	11:18:27
Air Blank	RFI*	11:18:48
Air Blank	IPS**	11:18:58

^{*}RFI Detect

Not a Successfully Completed Test Sequence

3087 Bymo

^{**}Improper Sample

Location: TUCSON POLICE DEPT

Serial Number: 80-002261

02/26/2007

11:19:05

40C7

Standard Lot#: 627101G

Last Changed By: T. GALLEGOS #28847

QAS: T. GALLEGOS #28847

TUCSON PD CRIME LAB

Operator: T. GALLEGOS #28847

TUCSON PD CRIME LAB

Subject: SQAP, SQAP

DOB: 11/11/1111

Sex: F Weight: 111

15 Minute Deprivation Period? Yes

Test	g/210L	Time
Air Blank	0.000	11:19:54
Diagnostic Test	Pass	11:20:21
Air Blank	0.000	11:20:49
0.100 Cal Check	0.100	11:21:08
Air Blank	0.000	11:21:37
Subject Test	0.105*	11:24:46
Air Blank	0.000	11:25:18
Air Blank	0.000	11:25:45
Subject Test	XXX**	11:26:06
Air Blank	0.000	11:26:40

^{*}Deficient Sample

Begin new deprivation period

Not a Successfully Completed Test Sequence

^{**}Invalid Sample

Location: TUCSON POLICE DEPT

Serial Number: 80-002261

02/26/2007 _____

11:27:02

Standard Lot#: 627101G

Last Changed By: T. GALLEGOS #28847

QAS: T. GALLEGOS #28847

TUCSON PD CRIME LAB

Test	g/210L	Time
Air Blank	0.000	11:27:30
Cal Check	0.100	11:27:49
Air Blank	0.000	11:28:18

EXHIBIT G-2

THIS REPORT PREPARED PURSUANT TO DUTY IMPOSED BY A.A.C. R13-10-104(A)

ARIZONA DEPARTMENT OF PUBLIC SAFETY

oof 7

STANDARD QUALITY ASSURANCE PROCEDURES INTOXILYZER MODEL 8000

154 mm

STANDARD CALIBRATION CHECK PROCEDURE

QA	Spec	iali	st 1evry hallegos 2884AGENCY Tucson Police Department 26-2007 TIME 1112
DA:	re	2.5	26-2007 TIME 1112
Int	coxil	yzer	26-2007 TIME 1112 Serial # 80-00226/ Location DVI HQ
(·			Ensure that gas tank is attached to instrument and contains a standard alcohol concentration solution 0. 100 AC. OR
	/		Pour a standard alcohol concentration solution AC, into a clean dry simulator and assemble the simulator. Ensure that a tight seal has been made. Turn on the simulator and allow temperature to reach $34^{\circ}\text{C} \pm 0.2^{\circ}\text{C}$
(\	<i>'</i>)	2.	Intoxilyzer 8000 display reads "PUSH BUTTON TO START"
(<i>/</i>)		Go to the "Control Testing Menu". Select "D" for dry control test or "W" for wet control test. After selection is made press ENTER.
(L		4.	Air blank completed.
()	,)	5.	Calibration check completed. Test results 0. 100 AC.
(V	/)	6.	Air blank completed.
(<i>)</i>)	7.	Remove printed record. Attach the record to the completed checklist.
SIC	GNATU	JRE	Luybally

DPS Form Exh G-2 (Rev. 05-01)

Location: TUCSON POLICE DEPT

Serial Number: 80-002261

11:11:42 02/26/2007

Standard Lot#: 627101G

Last Changed By: T. GALLEGOS #28847

QAS: T. GALLEGOS #28847 TUCSON PD CRIME LAB

Test	g/210L	Time
Air Blank	0.000	11:12:09
Cal Check	0.100	11:12:28
Air Blank	0.000	11:12:57

Pursuant to section 28-1327, Arizona Revised Statutes, this document is a certified duplicate of the information contained in computer storage devices of the Tucson Police Department.